

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-3527	DATE	Dec. 9, 2022
MANUFACTURER	Kawasaki Motors Corporation Japan , Ltd.		
DESCRIPTION OF DEFECT	The plunger in the camshaft-chain tensioner can lock up during usage due to deterioration of internal parts. Continuous use in this condition can result in loss of engine power during use.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
ZXT00N	「Ninja H2」	2015～2016	1057	
ZXT00X	「Ninja H2」	2017～2018	202	
TOTAL			1259	