

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-3519	DATE	December 8, 2022
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to a crack in the lubricating oil pipe of the turbocharger, oil leak will happen, which may cause oil smell in the passenger compartment and a warning light-on. At the worst case, there will be a risk of smoking by the leaked oil.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-DFM5P	ALPINE A110	2019-2020	96
7BA-DFM5P1	ALPINE A110	2020	12
ABA-BBM5P	MEGANE R.S.	2019-2020	159
7BA-BBM5P	MEGANE R.S.	2019-2020	504
			771