

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3526	Date	December 8, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In certain conditions, there is a possibility that the windscreen wiper may sporadically not work until the next ignition cycle due to the improper software of onboard supply control unit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AUCHH	VW Golf GTI/162kW	2016	1
ABA-AUCJXF	VW Golf R 2.0/206kW	2016	3
DBA-AUCJZ	VW Golf 1.2/77kW	2016	21
DBA-AUCPT	VW Golf 1.4/103kW	2016	4
		Total	29