

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3577	DATE	28 <sup>th</sup> Feb 2023
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	Under high ambient temperature and slow moving traffic situations, the maximum operating temperature of the radiator fan can be exceeded, leading to a malfunction of the fan motor. If the rider ignores the instrument warning light and continues to operate the motorcycle at low speed, coolant may be displaced.		

2BL-PSJ1200	Speed Triple RS	2022	292
8BL-PSJ1200	Speed Triple RS		19
	Speed Triple RR		155
		TOTAL	166