## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic / Import Vehicles

CAMPAIGN No.	GAI 3564	DATE	Feb. 20, 2023	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer: SCANIA JAPANA Co. Ltd. )			
DESCRIPTION OF DEFECT	There have been instances of rubber seals missing from the main connector to the Exhaust Emission Control System unit at production line of a parts manufacture.  It may occur water ingress, which can cause corrosion in the unit pins and thus impair the electrical function of the unit. In the worst case, illuminate warning lamp and activate engine torque reduction function.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2021-2022	6
		TOTAL	6