

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3569	DATE	20 February, 2023
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a temporary screw connection assembly problem, existing threaded connections on the camshaft controller can become strained to such an extent that the function of the camshaft controller cannot be guaranteed over the service life of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-970M48A	Panamera S	2010	2
	Panamera 4S		2
Unknown	PANAMERA	2010-2012	93
	CAYENNE	2010-2012	47
		Total	144