

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3558	DATE	February 2, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	The gateway control unit may be damaged by moisture entering under the rear seat bench. This may be caused by liquids spilt in the area of the rear seat bench. Damage to the gateway control unit may have effects on various vehicle functions. Restricted functions relating to this are indicated by warning messages in the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F2DJPA	Audi RS7 SB Air-Suspension	2021-2022	71
3AA-F2DJPF	Audi RS6 Avant	2021-2022	102
3AA-F2DJPL	Audi RS6 Avant Air-Suspension	2021-2022	106
3AA-F2DJPS	Audi RS7 SB	2021-2022	82
3AA-F2DKMA	Audi S7 SB	2020-2022	109
3AA-F2DKML	Audi S6	2020-2022	188
3AA-F2DKNF	Audi A6 45Tq	2020-2022	1,069
3AA-F2DKNS	Audi A7 SB 45Tq	2020-2022	714
3AA-F2DLZF	Audi A6 55Tq	2021-2022	45
3AA-F2DLZS	Audi A7 SB 55Tq	2021-2022	86
3CA-F2DFBF	Audi A6 40TDIq	2020-2022	977
3CA-F2DFBS	Audi A7 SB 40TDIq	2020-2022	438
AAA-F2DLZF	Audi A6 55Tq	2019-2020	1,126
AAA-F2DLZS	Audi A7 SB 55Tq	2019-2020	1,282
		Total	6,395