

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3553	DATE	January 30 <sup>th</sup> , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	There is a possibility that the degreasing treatment was insufficient on the oil pan sealing part of the engine, and that the liquid sealant was not applied to the correct location. As a result, there is a risk of engine oil leakage, and in some cases, a check control message may be displayed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-22BY20	「BMW 218d Active Tourer」	2022	194
		TOTAL	194