

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3554	DATE	January 30 <sup>th</sup> , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A manufacturing defect may have occurred in the process of cells for HV battery and therefore the wrapping of internal cell foils might be damaged. This may lead to a malfunction in the high-voltage battery, and in very rare cases, this can lead to discharge of the cell and in the worst case to a thermal event.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-8P06	「BMW i3」	2019 – 2020	2
		TOTAL	2