

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3549	DATE	26 January, 2023
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	<p>There is a possibility that the air-spring strut at the left and right of the front axle was not manufactured according to specifications on the affected vehicles.</p> <p>This can cause the circlip on the top of the strut to come loose and release the air in the air spring. The driving characteristics of the vehicle may be affected, increasing the risk of an accident.</p> <p>For this reason, the air-spring strut at the left and right front axle must be checked and replaced depending on the test result.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1NA1	Taycan	2021	1
ZAA-J1NA2	Taycan 4		1
		Total	2