

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3552	DATE	26 , Jan, 2023
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Incorrect bonding of the rear bonnet glass panels may lead to adhesion issue that could result in a detachment. The rear bonnet glass panels could fully detach from the vehicle, creating a road hazard and increasing the safety-risk of a crash for following traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7AA-47L541	Countach	2022	13