

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3592	DATE	27 March, 2023
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	<p>On the affected vehicles, moisture can enter the additional climate control pump control unit and cause malfunctions in the passenger compartment temperature control and when the engine residual heat function is activated.</p> <p>Over the service life of the vehicles, such malfunctions can lead to short circuits and cause visible damage to the additional pump successively to the wiring harness plug.</p> <p>If the damage progresses, an unnoticed short circuit can lead to an increased risk of smouldering and fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-G2K40A	Panamera GTS	2019-2020	347
3BA-G2ML1	Panamera	2021	141
3BA-G2ML2	Panamera 4	2021	65
3BA-G2MR	Panamera GTS	2021	148
3BA-G2MS	Panamera Turbo S	2021	27
7BA-G2NL2X	Panamera 4	2021	2
ABA-G2H29A	Panamera 4S	2017	215
ABA-G2H29AX	Panamera 4S	2017	1
ABA-G2H30A	Panamera Panamera 4	2017	109
ABA-G2H30AX	Panamera 4	2017	1
ABA-G2H40A	Panamera Turbo	2017	109
ABA-G2H40AX	Panamera Turbo	2017	8
ABA-G2J29A	Panamera 4S	2018, 2020	313
ABA-G2J29AX	Panamera 4S	2018, 2020	15
ABA-G2J30A	Panamera Panamera 4	2018-2020	1433
ABA-G2J30AX	Panamera 4	2018-2020	45

ABA-G2J40A	Panamera Turbo	2018, 2020	272
ABA-G2J40AX	Panamera Turbo	2018, 2020	5
		Total	3256