## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic / Import Vehicles

CAMPAIGN No.	GAI 3590	DATE	Mar. 17, 2023	
MANUFACTURE	SCANIA CV AB / Volgren Australia Pty Ltd.			
	(Japanese Importer: SCANIA JAPANA Co. Ltd. )			
DESCRIPTION OF DEFECT	Due to inadequate software in the control units which controls the front lighting, brake lights, passenger compartment lighting, air conditioning and door, the safety function may be activated when an increase in internal current is detected. As a result, control signals may be intermittently interrupted and, in the worst case, the front lights and brake lights may not illuminate or flash, thus failing to meet safety standards.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	SV OPTIMUS	2018	29
		TOTAL	29