

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3587	DATE	2023/3/15
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain vehicles of the C-Class (205 platform), E-Class (213 platform), CLS (257 platform), E-Class Coupe (238 platform), GLC (253 platform), S-Class (222 platform), each with M264 gasoline engine and 48V technology, at low engine speeds and high loads the powertrain software could misinterpret a rotational irregularity of the crankshaft. In this case a misfire would erroneously be detected and the engine power would be reduced. As a result the malfunction indicator lamp (MIL) would be activated contrary to OBD regulations. Furthermore, local legal requirements regarding emission values might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-205077	C200	2019	1,804
DAA-205077C			423
5AA-205077			1,428
5AA-205077C			249
-205042-			1
DAA-205078	C200 4MATIC		83
DAA-205078C			10
5AA-205078			289
5AA-205078C			54
DAA-205277	C200 Wagon		915
DAA-205277C			217
5AA-205277			596
5AA-205277C			95
DAA-205278	C200 4MATIC Wagon		24
DAA-205278C			3
5AA-205278		176	
5AA-205278C		31	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4AA-213077C	E200	2019	804
4AA-213078C	E200 4MATIC		172
4AA-213277C	E200 Wagon		204
4AA-213278C	E200 4MATIC Wagon		62
		TOTAL	7,640