

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	Gai-3588	DATE	2023/3/15
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain right-hand drive C-Class (205 platform) vehicles the bolting of the 48V ground connection in the engine compartment might be fastened with an insufficient torque. In this case, the cable lug of the ground line might not be fixed correctly. Subsequently, the electric resistance of the connection might increase. In combination with the high electrical currents potentially flowing through this connection, the temperature in this area might increase. As a consequence, a risk of fire cannot be ruled out completely.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-205077	C200	2020	2,145
		2021	64
5AA-205077C		2020	364
		2021	21
5AA-205078	C200 4MATIC	2020	416
		2021	15
5AA-205078C		2020	47
		2021	5
		TOTAL	3,077