

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3579	DATE	March 13, 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate software, a misdiagnosis can occur sporadically at the BMU (SME). This may lead in very rare cases to an unplanned charging interruption or a shutdown of the high-voltage system. If the fault occurs while driving, it may result in a brief loss of power, or the vehicle may roll out slowly. However, a restart of the vehicle allows to continue driving. In the event of a malfunction, the driver is informed by a check control message.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-72AW44	「BMW i4 eDrive40」	2021 - 2022	465
ZAA-32AW89	「BMW i4 M50」	2021 - 2022	100
ZAA-52EJ89	「BMW i7 xDrive60」	2022	3
ZAA-42DU44	「BMW iX3 M Sport」	2021 - 2022	740
ZAA-12CF89S	「BMW iX xDrive40」	2021 - 2022	372
ZAA-22CF89A	「BMW iX xDrive50」	2021 - 2022	184
ZAA-31CF93A	「BMW iX M60」	2022	8
		TOTAL	1,872