

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3574	DATE	March 7 th , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the case of some diesel vehicles, EGR (Exhaust-Gas-Recirculation) cooler could become leaky over time. The glycol-leakage in combination with typical soot deposits and the high temperatures normally present in the EGR module, might result in smoldering particles. This could lead in very rare cases to the melting of the intake manifold and in extremely rare cases result in a possible fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-1S20	「BMW 118d」	2017～2018	4
LDA-JC20	「BMW 523d」	2018	1
LDA-TX20	「BMW X3 xDrive 20d」	2017～2019	3
		Total	8