

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3608	DATE	28 th Apr 2023
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The improper securing of the left-hand brake disc may lead to its detachment from the front wheel assembly. The disc will be retained by the caliper body. This can cause a distraction and reduced braking performance, posing a significant safety risk.		

8BL- DHJ1200	Bonneville T120	2023	290
		TOTAL	290