

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	外-3597	DATE	21/4/2023
MANUFACTURER	Alfred Kärcher SE & Co. KG		
DESCRIPTION OF DEFECT	In the steering systems of the MIC 42, the strength of the spring pin that fixes the spline mechanism of the steering wheel is not sufficient enough. Therefore, if this vehicle is continued to be used, in the worst case, when a large force is continuously applied, the pin may be sheared and the steering operation may not be performed reliably.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED{ * }	NUMBER OF VEHICLE
MIC 42	Multipurpose Work Vehicle	S/N:200091 ~ 200303 15/2/2019 ~ 17/8/2021	5
(TOTAL 1 TYPES)	(TOTAL 1 MODELS)	TOTAL	5

[*] Range of recalled No. includes the number that is not subject to the recall.