

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3600	DATE	April 13, 2023
MANUFACTURE	Automobiles PEUGEOT DS Automobiles (Japanese Importer :Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	Due to bad balance of the rear driveshaft washers at the mounting, it may be able to move before the final assembly. The washer may break during usage and may contact with ABS sensor. As this consequence, noise may happen, ABS warning light may turn on, waraning message may be displayed and ABS functions may not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-P845G06H	「3008 HYBRID4」	2020-2021	380
3LA-X745G06H	「DS 7 CROSSBACK E-TENSE」	2020-2021	102
		TOTAL	482