

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3609	DATE	April 26, 2023
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The fuel tank may have a welding fault on the lid of the mounting hole for the suction jet pump. Due to driving vibration etc., this may lead to the formation of cracks at the weld seam, where the fuel may leak from.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3R30	B3 Biturbo	2016-2017	27
	B3S Biturbo	2017-2018	49
	B3 Biturbo Touring	2016-2017	6
	B3S Biturbo Touring	2017-2018	13
	B4 Biturbo Coupe	2016-2017	14
	B4S Biturbo Coupe	2018	37
	B4 Biturbo Cabrio	2016	3
	B4S Biturbo Cabrio	2017-2018	18
		TOTAL	167