

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3624	DATE	29.06.2023
MANUFACTURE	Ferrari SpA (Japanese Importer : Ferrari Japan K.K)		
DESCRIPTION OF DEFECT	In the fuel system, due to the insufficient consideration of galvanic corrosion at the design phase, galvanic corrosion may occur because of the contact between the different metals which are the fuel pipe (made of aluminum) between the right and left fuel tanks, and the high-voltage battery protection cover (made of fiberglass contains the stainless steel). Contact between this pipe and this cover could cause fuel leakage from the fuel pipe. In the worst case, this could lead to fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-171K	296GTB 296GTS	2022-2023	85
		TOTAL	85