

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 3626	DATE	29, Jun, 2023
MANUFACTURE	SCANIA CV AB / Van Hool nv. (Japanese Importer: SCANIA JAPANA Co. Ltd.)		
DESCRIPTION OF DEFECT	<p>Due to insufficient clearance between the driver's seat and the interior trim behind the driver's seat, the cover of the seatbelt take-up device and the interior trim may interfere with each other when the driver's seat is lowered to the very end of the vehicle when getting in and out of the vehicle. If the driver's seat continues to be used in this condition, in the worst case scenario, the seatbelt may not be able to be pulled out due to interference within the belt winder.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	-	2018-2020	41
		TOTAL	41