

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3638	Date	June 29, 2023
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	The suspension strut mounting might be deformed due to a failure in the assembly process of the press-fit nuts. A deformed suspension strut mounting may lead to an insufficient screw connection of the strut mount. The screw might loosen which may reduce the lane stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-CDDLA	Golf 1.0/81kW	2023	3
3AA-CDDLAV	Golf Variant 1.0/81kW	2023	4
3AA-CDDFY	Golf 1.5/110kW	2023	2
3AA-CDDFYV	Golf Variant 1.5/110kW	2023	9
3BA-CDDNP	Golf GTI 2.0/180kW	2023	27
3BA-CDDNFF	Golf R 2.0/235kW	2023	2
3DA-CDDTSV	Golf Variant TDI/110kW	2023	5
3DA-CDDTT	Golf TDI/110kW	2023	8
3BA-5NDNFF	Tiguan R 2.0/235kW	2023	12
3BA-A1DPC	T-ROC 1.5/110kW	2023	1
		Total	73