VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3639	Date	June 29, 2023	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	On ID.4 vehicles of a limited production period there is a possibility that, because of an incorrectly fitted membrane, humidity could get into the electronics of the outer door handles. At vehicle speeds of below 15 km/h the humidity that has penetrated the electronics can lead to a vehicle door unexpectedly opening if the vehicle is subject to high lateral forces.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ZAA-E2EBJ	ID.4	MY2022	506
		Total	506