

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3618	DATE	June 23th,2023
MANUFACTURE	Bombardier Recreational Products Inc. Japanese Importer : BRP Japan		
DESCRIPTION OF DEFECT	Potential contamination or component friction in the brake light switch may cause the brake lights to stay illuminated, even when the brake pedal is not pressed. If the brake lights remain illuminated, it can fail to alert other motorists of the rider's intention and increase the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NBD	SPYDER RT	11 Dec 2019 to 18 Jan 2023	415
2FF 2FG 2HH 2JG	Ryker	18 Jan 2022 to 17 Jan 2023	146
		TOTAL	561