## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

		1		
CAMPAIGN No.	Gai-3631	DATE	2023/6/22	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )			
DESCRIPTION OF DEFECT	On certain GLE and GLS vehicles (167 platform), the air conditioning drain hoses might be			
	incorrectly fitted in the vehicle. In this case, condensation water from the air conditioning			
	might enter the passenger compartment.			
	If condensation water enters into the driver and passenger side footwells, it might cause			
	corrosion and/or short circuits to the electrical components installed in this area.			
	In addition, the performance of other features of the vehicle could be impacted such as the			
	automatic emergency call (eCall) might not be available, the vehicle might not be able to be			
	unlocked and/or started and the engine limp-home mode might be activated during driving.			
	This increases the potential risk of injury or a crash.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-167119C		2019	63
	GLE300d 4MATIC	2020	247
3DA-167123	GLE400d 4MATIC	2019	68
		2020	800
3DA-167323			363
	GLE400d 4MATIC Coupe	2021	1
5AA-167159		2019	58
	GLE450 4MATIC	2020	381
		2021	1
4AA-167161	Mercedes-AMG GLE53 4MATIC+	2020	122
4AA-167361	Mercedes-AMG GLE53 4MATIC+ Coupe		88
7AA-167189	Mercedes-AMG GLE63S 4MATIC+		10
7AA-167389	Mercedes-AMG GLE63S 4MATIC+		3
	Coupe	2021	1
3DA-167923	GLS400d 4MATIC	2020	647
4AA-167986	GLS580 4MATIC		167
7AA-167989	Mercedes-AMG GLS63 4MATIC+		4
		TOTAL	3,024