

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles )

CAMPAIGN No.	Gai-3633	DATE	2023/6/22
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain S-Class (223 platform) vehicles, the sealing of the front wall might not meet the tightness requirements.</p> <p>In this case, a high water exposure might lead to water ingress into the vehicle's interior and cause corrosion on the electrical contacts and or short circuits or leakage currents.</p> <p>As a result, the function of the PreSafe system might be impaired possibly increasing the risk of injury in the event of a crash. In addition, it may not be possible to restart a parked vehicle.</p> <p>Furthermore, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-223033	S400d 4MATIC	2021	267
3DA-223133			45
5AA-223063	S500 4MATIC		587
5AA-223163			108
		TOTAL	1,007