

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3611	DATE	May 31 st , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate assembling process, the outer seat belts in the second row of seats may have been slightly jammed at the bottom by the C-pillar trim panels. In this case, the restraint function could be impaired and the safety of the passengers could not be guaranteed in certain accident situations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-62BX15	「BMW 218i Active Tourer」	2022 - 2023	677
3DA-22BY20	「BMW 218d Active Tourer」	2021 - 2023	677
3BA-52EE20	「BMW X1 xDrive20i」	2022	114
		TOTAL	1,468