

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3610	DATE	May 25, 2023
MANUFACTURE	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	For the coolant pump for air conditioning, it is possible that moisture comes into electric connector inside the coolant pump and electrical short circuit is made due to inappropriate design for internal vacuum to be released. Therefore, defrosting performance will be reduced during engine idling because the coolant pump stops operating. If this condition persists, the electric connector of the pump will overheat and it may catch fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BFDBD	Continental GT Speed	2018 – 2018	2
ABA-BCDDB	Continental GT	2018 – 2020	362
7BA-BDDDB	Continental GT Convertible	2019 – 2020	48
		TOTAL	412