

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3599	DATE	May 19th 2023
MANUFACTURE	Bombardier Recreational Products Inc. Japanese Importer : BRP Japan		
DESCRIPTION OF DEFECT	<p>Currently, the 2 side rear indicator lights on Ryker will flash automatically when vehicle is reversing. However, use of the rear indicator lights that automatically flash conflicts with MLIT Details about "other light usage".</p> <p>To follow an instruction from MLIT, BRP will release a recall on Ryker with solutions below to correct this non-compliance status of rear indicator light use.</p> <p>A light setting for Japan market will be released to make sure 2 side rear indicator lights will be completely turned off while the vehicle is reversing.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2FF	Can-Am RYKER600	5 Feb 2019 to 5 Jul 2022	656
2FG	Can-Am RYKER900		
2GG,2HH	Can-Am RYKER RALLY		
2JG	Can-Am RYKER SPORT		
		TOTAL	656