

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	Gai-3606	DATE	2023/5/11
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain G-Class (463 platform) vehicles, the front axle wiring harness might come in contact with the auxiliary oil cooler. In this case, the wiring harness might chafe on the auxiliary oil cooler and be damaged over time. As a result, ABS and ESP functions could be impaired. This might increase the risk of an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-463349	G350d	2019	1,124
		2020	2,000
		2021	1,192
3DA-463350	G400d	2020	45
		2021	4,315
ABA-463260	G550	2019	550
3BA-463260		2020	2
		2021	220
ABA-463276	Mercedes AMG G63	2019	138
		2020	2,204
3BA-463276		2020	942
		2021	408
		2021	2,565
		TOTAL	15,705