

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3658	DATE	2023/7/27
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain S-Class (223 platform) vehicles, the monitoring software of the Electronic Stability Program (ESP) might not meet specifications.</p> <p>Under certain conditions, the ESP monitoring software could erroneously determine a fault condition. In that event, the ESP fault response would limit the functionality of the vehicle's dynamics control systems (ABS, ASR, ESP, EBD) and the speedometer would indicate a speed of 0 km/h (0 mph), regardless of the actual vehicle speed. This might increase the risk of a crash.</p> <p>Legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-223033	S400d 4MATIC	2022	464
		2023	365
3DA-223133		2022	16
		2023	30
5AA-223063	S500 4MATIC	2022	388
		2023	421
5AA-223163		2022	199
		2023	141
4AA-223076	S580 4MATIC	2022	202
		2023	199
4AA-223176		2022	236
		2023	187
5LA-223169	S580e 4MATIC	2022	44
		2023	19

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7AA-223976	Mercedes-Maybach S580 4MATIC	2022	93
		2023	45
7BA-223979	Mercedes-Maybach S580 4MATIC	2022	1
		2023	1
		TOTAL	3,051