## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3659	DATE	2023/7/27		
MANUFACTURE	Mercedes-Benz AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )				
DESCRIPTION OF DEFECT	On certain S-Class (222 platform) and S-Class coupé/cabriolet (217 platform) vehicles the fuel line connection of the low pressure fuel line might not meet specifications.  In this case, accelerated ageing over time in the area of the fuel line connection might occur and thus impair the tightness of the connection. Subsequently, single drops of fuel might leak in the engine compartment, leading to clearly perceptible fuel smell. An accumulation of fuel and therefore a risk of fire can be excluded. However, local legal emission limits regarding fuel evaporation might not be met.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-222183		2018	741
		2019	125
	S560	2020	218
DBA-222183C		2018	50
		2019	14
DBA-222186	S560 4MATIC	2018	974
		2019	98
		2020	125
DBA-217383C	S560 Coupe	2018	40
		2019	19
		2020	29
7BA-217383C		2021	3
DBA-217386	S560 4MATIC Coupe	2018	40
		2019	20
		2020	24
7BA-217386		2021	6

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-217483	S560 Cabriolet	2018	23
		2019	26
		2020	17
7BA-217483		2021	4
DBA-222983C	Mercedes-Maybach S560	2018	60
		2019	51
		2020	46
DBA-222986	Mercedes-Maybach S560 4MATIC	2018	68
		2019	40
		2020	54
		TOTAL	2,915