

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**

**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3647	Date	Jul. 26, 2023
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	Due to improper Battery Energy Control Module (BECM) software, vehicles have experienced thermal overload which may show as smoke or fire, that may occur underneath the vehicle where high voltage traction battery is located.  Update to the Battery Energy Control Module (BECM) software.		

Type	Commercial name	Model year recalled	Number of vehicles
ZAA-DH1AA	I-PACE	2019-2022	283
ZAA-DH1CA			84
Unknown			1
		2019-2022	368

(JIS A4 size)