

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-3641	DATE	July 11, 2023
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	With regards to the vehicles with front air suspension, due to the inappropriate anchorage fixing bolt tightening torque which holds the air springs on the front axle, the bolt may become loose by vehicle vibration. Thus, if the vehicle continues operation under these conditions, the bolt may fall off, after which the anchorage may come off from its original position. In the worst case, the vehicle may lose driving stability and might cause an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-4K2TDA1	FH	2022	6	
2KG-4K2TEA1		2022	9	
2DG-4K3RTF1		2022	30	
2DG-5K2TDA1 2KG-5K2TDA1		2022	2	
2DG-5K2TEA1 2KG-5K2TEA1		2022	14	
2DG-5K4RTF1		2022	4	
2DG-5K4TBA1		2022	2	
2DG-5K4TCA1		2022	1	
		TOTAL	68	