

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-3601	DATE	September.1, 2023
MANUFACTURER	StreetScooter GmbH (Japanese Importer: B-ON K.K.)		
DESCRIPTION OF DEFECT	SAFETY RECALL: Certain 2019 Year D17 Vehicles - Replace both Left and Right rear brake calliper. The surface treatment of the threaded pins of the brake calliper as the root cause for the different the response behaviour of the wear-related adjustment mechanism. The initial surface treatment can cause an increased stick-slip effect. This can cause an uneven distribution of the handbrake force between left and right and in worst case not meet the required standards for the handbrake.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-D17SMG180	StreetScooter D17	2019	489 units
TOTAL			489 units