

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-3655	DATE	Aug 31, 2023
MANUFACTURER	RENAULT SAS (Japanese Importer: Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	In the drive circuit of the cooling fan motor, an unnecessary diode installed due to improper circuit design. Therefore, the back electromotive force generated to a diode when the fan motor is spinning. and in the worst case, a burning smell may occur. In addition, the fuse capacity of the drive circuit was inappropriate setting, the fuse will not blow if the circuit shorted and current exceeds the allowable amount, In the worst case, wiring may be damaged and lead to fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-DFM5P	Alpine A110	2018	79
		TOTAL	79