


VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3635	DATE	Aug 24, 2023
MANUFACTURE	BYD (Japanese Importer: BYD Auto Japan Inc.)		
DESCRIPTION OF DEFECT	In the lights, there is an answerback function that the animation of the position lights and taillights for more than three seconds in conjunction with unlocking the vehicle. In this condition, due to the improper software program, the sequence of operating times is prolonged and does not meet the requirements of Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-SC2EXSQ	ATTO 3	2022-2023	529
		TOTAL	529

## 【記入例】



### VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-	DATE	July 21, 2005
MANUFACTURE			
DESCRIPTION OF DEFECT	<p>上段には自動車製作者の名称を記載して下さい。 下段には届出者の名称を記載して下さい。</p> <p>日付の記載は、月（英字）日（アラビア数字）、西暦の順で<b>リコール届出年月日</b>を記載して下さい。（リコール開始年月日を記入しないで下さい。）</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		<p>製作年のみの記載。</p> <p>2005-2006</p>	
		TOTAL	

Domestic Vehicles : 日本国内車両

Import Vehicles : 輸入車両

CAMPAIGN No. : 届出番号

DATE : 届出年月日

MANUFACTURE : 製作者名

DESCRIPTION OF DEFECT : 不適合状態

TYPE : 型式

COMMERCIAL NAME : 通称名

MODEL YEAR RECALLED : 対象車両の製作年

NUMBER OF VEHICLE : 対象車両数