

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(Import)~~ Vehicles

CAMPAIGN No.	gai-3668	DATE	August 21st, 2023
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	In the engine cooling system, the fuse of the electric fan may blow due to overcurrent due to improper design of the electric fan motor for cooling the engine. Continuing to drive as it is may cause overheating, and in the worst case, the engine may stop and restart may not be possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-3G00	Diavel V4	2023	69
		TOTAL	69