

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3653	Date	Aug. 01, 2023
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	7-seat vehicles where the second row left seat frame may have a latch installed with a defective weld. In vehicles that have an defective weld on the second row left seat frame latch, the seat may not be correctly secured. If the seat is incorrectly secured, in the event of a crash or sudden braking, the seat will move forward and upwards. This increases the risk of injury to first and second row seat occupants. Inspect/Replace the seat frame.		

Type	Commercial name	Model year recalled	Number of vehicles
3BA-LKB447A	Range Rover	2022	2
		2022	2

(JIS A4 size)