

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3694	DATE	September 29, 2023
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	Some vehicles may have been built with an incorrectly assembled steering column intermediate shaft which may potentially disconnect from the U-joint. Driver may notice play in steering and/or noise when turning prior to the intermediate shaft disconnecting. A disconnected intermediate shaft may result in a loss of steering control which can cause a vehicle crash without prior warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-WL20	「Grand Cherokee」	2023	8
3LA-WL20A	「Grand Cherokee」	2023	13
7BA-WL20	「Grand Cherokee」	2023	45
7BA-WL36L	「Grand Cherokee L」	2021-2023	157
7BA-WL36LA	「Grand Cherokee L」	2021-2023	40
7LA-WL20A	「Grand Cherokee」	2022	1
		TOTAL	264