## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	Gai-3695	DATE	September 29, 2023	
MANUIFACTURE	FCA US LLC			
MANUFACTURE	(Japanese Importer : Stellantis Japan Ltd. )			
DESCRIPTION OF DEFECT	Some vehicles may have been built with an incorrectly installed rear coil spring which may detach from the vehicle while driving. Rear coil springs that detach from the vehicle while driving may result in a hazard to operators and occupants of other vehicles which can cause such vehicles to crash without prior warning and/or may result in injury to vulnerable road users.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3LA-WL20	「Grand Cherokee」	2023	129
7BA-WL20	「Grand Cherokee」	2022–2023	587
7BA-WL36L	「Grand Cherokee L」	2021–2023	1268
		TOTAL	1984