

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3690	DATE	2023/9/28
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain EQS (297 platform) vehicles, the bolting of the rear seat belt buckles might be fastened with an insufficient tightening torque.</p> <p>In this case, the bolts of the rear seat belt buckles might come loose due to vibrations while driving or in the event of a crash. As a result, the restraint effect of the rear seat belts might be impaired, increasing the risk of injury for vehicle occupants.</p> <p>Legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-297123	EQS450+	2023	2
ZAA-297155	Mercedes-AMG EQS53 4MATIC+		1
		TOTAL	3