

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3663	DATE	Sep. 27th, 2023
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	The radiator hose joint can potentially leak due to inadequate design of the joint. During high vehicle loads (ex. Track running) the coolant system goes through cycles of higher pressures and heat where the joint is expanding and contracting. After prolonged exposure to these driving loads the hose joint can potentially lose sealing/sufficient contact to cause a leak of coolant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P13SP	McLaren 600LT Coupe McLaren 600LT Spider	2019 - 2020	170
		TOTAL	170