

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3672	DATE	September 13, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	It is possible that the guide channel for the front passenger's airbag may not have been welded to the dash panel according to specifications on a number of Audi TT vehicles manufactured within a specific period. In the event of an accident which causes the airbags to deploy, this could result in damage to the front passenger's airbag, potentially impairing the airbag's ability to protect the passenger. An increased risk of injury cannot be ruled out in such cases. For safety reasons, it is therefore necessary to check the serial number of the dash panel and replace it if required.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-FVDKZ	Audi TT 40T	2023	26
3BA-FVDNFF	Audi TTS	2023	36
3BA-FVDNPF	Audi TT 45Tq	2023	25
		Total	87