

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3674	Date	Sep. 5, 2023
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	As the Headlamps, where the instrument cluster displays a critical warning message "Headlights fault detected" and the headlamp assemblies may fail when the vehicle is started or switched off, and does not recover on any subsequent ignition cycle. Update the Headlight control module.		

Type	Commercial name	Model year recalled	Number of vehicles
3BA-LK9447A	Range Rover	2023	213
3BA-LKB447A			126
3CA-LK93WA			154
3LA-LK934A	Range Rover PHEV		28
3LA-LKB34A			4
3AA-L123UA	Range Rover Sport		175
3CA-L123WA			267
			2023

(JIS A4 size)