

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3693	Date	Sep. 29, 2023
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Defect	Transmission mounting bolts may have been tightened to insufficient torque. Then the Transmission holding may be loosened and noise or excessive vibration can appear.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-JW2	「910」	2021 to 2023	65
YDP-JC3	「914」	2021 to 2023	35
YDR-SL4	「920」	2021 to 2023	51
		TOTAL	151