VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

	-	D	omestic Import Vehicles
CAMPAIGN No.	GAI 3719	DATE	31.Oct.2023
MANUFACTURE	BMW		
	(Japanese Importer)		
DESCRIPTION OF DEFECT	BMW Motorrad has determined that due to an incorrectly set encoding parameter in the software, the daytime driving lights are only activated at 32% of the required brightness. This does not comply with the legally required brightness for daytime driving lights.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-R12MB	R1250RS	2023	378
8BL-S10AB	M1000R	2023	308
		TOTAL	686