

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3648	DATE	October 26, 2023
MANUFACTURE	DS Automobiles (Japanese Importer :Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	Due to stress to the tail lamp, water can enter through the connecting portion between the rear lamp housing and glass into inside of the lump. This may cause, in the worst case, not-illumination of the lump.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-X74AH01	「DS 7」	2019 - 2020	159
7BA-X745G06	「DS 7」	2019 - 2020	128
ABA-X745G06	「DS 7」	2018 - 2019	316
LDA-X74AH01	「DS 7」	2018 - 2020	547
		TOTAL	1,150